
Notice to All Mariners!
GCI
Keep Alaska Online, Catch Fish, Not Cables
Submarine Fiber Optic Cables have been installed through Cook Inlet. Avoid bottom contact with any gear or anchors on top of the installed cables.
Report any incidents to:
907-868-5555
KKFL1
(use chart 16663)
Fire I
(330)
TURNAGAIN ARM
Chickaloon Bay
Trading Bay
Anchorage
Pt Woronzof
Pt Campbell
Pt Mac Kenzie
Pt Possession
Moose Pt
Gray Cliff
Boulder Pt
Beluga
Chuitna R
North Foreland
Mequawkie
Old Tyonek
Ladd
Susitna
Mt Susitna
Alexander
Cottonwood
Knik
Lake Lucille
Eagle Cr
Rainbow Cr
Indian Cr
Bird Cr
Glacier Cr
Hope
Sunrise
Sixmile Cr
Resurrection Cr
Big Indian Cr
Quartz Cr
Placer
Polar B
AUTA
CAUTION
The Cook Inlet area is affected by land uplift due to forces such as post-seismic crustal rebound. As a result, the tidal datums including mean lower low water, the plane of reference used for depth soundings, have changed throughout this region. Tidal datums were updated in 1999 and depths of 11½ fathoms or less on this chart were adjusted accordingly to account for this uplift. As the uplift rates can only be estimated and areas continue to rise, depths may be shoaler than charted. Mariners are urged to exercise caution.
Fl 6s 294ft 9M
East Foreland
Nikiski
F RWG 127ft 10M
Salamatof
AERO R Bn
Kenai
KKFL2
Kenai R
Skilak L
Kenai Lake
Upper Trail Lake
Trail Cr
Kasilof
Iso 6s 30ft 6M
C Kasilof (May 1 to Nov 1)
PARABOLIC ANT
Ninilchik
Fl 4s 5M
Trichkof
Seward
Resurrection R
Snow R
RESURRECTION BAY
Pilots
Rugged I
KKFL3
C Resurrection
Fl 6s 438ft 7M
Day Hbr
Pedersen Gl
Alaska R R